

IED Report

REL TO

CLASSIFICATION: SECRET RELEASABILITY: USA,

ACGU

BLAST-

TRACKING NUMBER: 20111114191638SMB3241

2011-Nov-DATE DISCOVERED:

14 19:16

699926

CALL SIGN: Make 2-1

REPORTING UNIT:

722nd OD Co EOD

PRIMARY SAFE

38SMB3241799925

SECONDARY SAFE Not

AREA(MGRS): Reported

AREA(MGRS):

Not

MGRS: 38SMB3241699926

EVENT TYPE: Reported

COALITION: KIA: WIA:

4

CIVILIAN:

KIA:

0

WIA:

0

KIA:

WIA:

0 0

HOST NATION:

Equipment Used

1

Team Data

SERVICE AFFILIATION:

EOD NOTIFICATION: 2011-Nov-14 19:16

EOD FOB DEPARTURE: 2011-Nov-14 19:30 EOD SCENE ARRIVAL: 2011-Nov-14 19:45

EOD SCENE

2011-Nov-14 23:43

EOD MISSION

2011-Nov-14 20:45

DEPARTURE: COMPLETE:

15-November-11 Page 1 of 3 SECRET//REL TO USA, ACGU

USCENTCOM FOIA 17-0112 107 08/08/2018



Site Data

SITE MARKED: Yes

MARKING DETAILS: pole marked with green tarp across the top approximately 10m

from blast seat

CIVILIAN ACTIVITY: Unknown

REFERENCE POINT: Not Reported

AIMING POINT DETAILS: pole marked with green tarp across the top

FIRING POINT DETAILS: Not Reported

FIRING POINT MGRS: Not Reported

LIGHT CONDITIONS: Night

WEATHER: Clear

ROUTE PATROL: N/A

CLEARED:

LAST TIME ROUTE

Not Reported

ANALYSIS: Not Reported

Devices

Device 1

DEVICE DESCRIPTION: EFP with unknown initiation system

MGRS: 38SMB3241699926

PLACEMENT: LOCATION: Road - Right

Side

CONTAINER: Other CONTAINER SUB-TYPE: Not Reported

HOW DEVICE WAS FOUND: Detonation WHO FOUND DEVICE: Not Applicable

ACTION TAKEN: Post Blast

EXPLOSIVE EFFECT: Blast

Fragmentation

MAIN CHARGE CONFIGURATION: Directional-EFP

CASUALTIES: Yes SUICIDE DEVICE: No FIRST RESPONDER TARGETED: No

15-November-11 Page 2 of 3

USCENTCOM FOIA 17-0112 108 08/08/2018



POST BLAST: Yes PARTIAL BUILD: No

Targets

TARGET PRECEDENCE: Primary AFFILIATION: Coalition

> COUNTRY: USA - UNITED **TARGET TYPE:** Military

STATES

DETAILS: Convoy INTENDED EFFECT: Anti-Armor

DESCRIPTION: IED targeted gunner of the vehicle

Initiators

TYPE: INITIATION SUB-TYPE: Not Unknown

Reported

INITIATION DETAIL: Not INITIATOR: Not

> Reported Reported

DTMF: Not ARMING: Not Reported Reported

MODEL: Not

MAKE: Not Reported Reported

RECEIVER REMOTED DISTANCE(M): RECEIVER REMOTED: Not

Reported

Munitions

Not Reported

15-November-11 Page 3 of 3 SECRET//REL TO USA; ACGU-

USCENTCOM FOIA 17-0112 109 08/08/2018



****SIGACT CLOSED****

SIGACT Report

TITLE: (EXPLOSIVE HAZARD) IED EXPLOSION RPT (Directional IED) 2/B/2-

325 AIR IVO (ROUTE MSR TAMPA): 1 CF KIA 2 CF WIA

TRACKING NUMBER: 20111114190038SMB3241099926

REPORT PRECEDENCE: Flash

CLASSIFICATION: SECRET RELEASABILITY: REL TO USA, FVEY

REPORTING UNIT NAME: USD-C G3 SIGACT

MANAGER

REPORT SOURCE:

Coalition

SPOT Section

UNIT NAME INVOLVED: 2/B/2-325 AIR CALL SIGN: Not Reported

TYPE OF INVOLVED UNIT: CF INVOLVED UNIT ACTIVITY: Tactical Convoy

INCIDENT REPORTED BY: Coalition Forces BATTLESPACE LEAD: Coalition

TIP REPORTED BY: Not Reported DTG CREATED (LOCAL): 2011-11-14

19:55:25

DTG OF INCIDENT (LOCAL): 2011-11-14 DTG UPDATED (LOCAL): 2011-11-15

19:00:00 16:43:20

Location

MGRS: 38SMB3241099926 ROUTE: MSR TAMPA

Events

EVENT TYPE: Explosive Hazard MODES OF ATTACK: Directional IED

EVENT CATEGORY: IED Explosion

15-November-11 Page 1of 7

USCENTCOM FOIA 17-0112



PRIMARY INTENDED OUTCOME: Anti-Personnel

SUICIDE?: No EFFECTIVE HIT?: No

COORDINATED ATTACK: No

COMPLEX ATTACK: No

COUNTER ATTACK: No

MEDEVAC REQUESTED: No

BLOWN IN PLACE: No

SUMMARY: USF REPORT

AT 14 1900 NOV 11, AN IED DETONATED ON THE LEAD VEHICLE (MAXPRO) OF A 2-325 AIR SUPPLY CONVOY TRAVELING SOUTH ON MSR TAMPA ENROUTE TO THE KAC FROM TAJI. SWT 8 WAS RETASKED TO THE SITE TO PROVIDE OVERWATCH. 2/B/2-325 AIR QRF, EOD, AND KBR RESPONDED TO THE SITE TO CONDUCT PBA AND PROVIDE RECOVERY SUPPORT. THE CONVOY MOVED PAST THE BLAST SITE APPROXIMATELY 200M AND STOPPED TO CONDUCT BDA. 2-325 AIR REPORTED 5 X USF WIA (3 X URGENT SURGICAL, 2 X UNK) AND REQUESTED MEDEVAC. AT 1935, IA ARRIVED ONSITE. (b)(1)1.4c

(b)(1)1.4c

MEDEVAC WAS WHEELS DOWN AT THE IED SITE AND AT 2004 THE CASUALTIES ARRIVED AT SATHER CSH FOR TREATMENT. AT 2000, MSR TAMPA WAS TURNED BLACK IVO CP 56A. AT 2008, QRF, EOD, AND KBR ARRIVED ON SITE. EOD CONDUCTED PBA AND INITIALLY ASSESSED THE IED AS AN EFP. ALL CASUALTIES WERE ASSESSED AT THE CSH. 3 X USF ARE NSI. 1 X USF SUFFERED CALF WOUND AND A BROKEN LEG (SI). 1 X USF SUFFERED MULTIPLE SHRAPNEL WOUNDS TO THE HEAD, GROIN, AND LEFT ARM AND WAS UNCONSCIOUS (VSI). AT 2200, DIVSURG REPORTED THE 1 X USF THAT WAS VSI DOW. MSR TAMPA RETURNED TO AMBER AT 0605. AT 2343, 2/B/2-325 AIR AND KBR ARRIVED AT TAJI WITH THE RECOVERED MAXPRO. EOD AND QRF COMPLETED SITE EXPLOITATION AND RETURNED TO TAJI AT 15 0008 NOV 11.

EOD ASSESSMENT: TM 2-1 RESPONDED TO AN IED BLAST IVO 38SMB 32416 99926. A 2ND PLT/B CO/2-325 AIR CONVOY WAS TRAVELING SOUTH ON MSR TAMPA WHEN THE LEAD VEHICLE WAS STRUCK BY AN EFP. 2-325 AIR SOLDIERS PERFORMED A SECONDARY SEARCH IOT CLEAR A HASTY LZ FOR MEDEVAC, AND CALLED FOR EOD TO RESPOND. THE EOD TEAM ARRIVED ON SCENE AND DISMOUNTED

15-November-11 Page 2of 7

(b)(1)1.4g

(b)(1)1.49 DAMAGE TO THE TARGET VEHICLE CONSISTED OF ARMOR PENETRATION ON THE TC SIDE AND EMBEDDED COPPER RESIDUE ON THE DRIVER SIDE INTERIOR WALL. FRAGMENTS OF COPPER FROM INSIDE THE VEHICLE WERE RECOVERED AS EVIDENCE. NO EVIDENCE OF THE INITIATION SYSTEM WAS FOUND. THERE WERE NO SECONDARY DEVICES OR EXPLOSIVE HAZARDS FOUND. THERE WAS ONE USF KIA AND FOUR USF WIA AS A RESULT OF THIS ATTACK.

IT IS THE EOD TEAM LEADER'S ASSESSMENT THAT THE IED WAS AN EFP WITH AN UNKNOWN INITIATION SYSTEM. THE STRUCK VEHICLE WAS IMPACTED NEAR THE TOP OF THE PASSENGER SIDE INDICATING A HIGH ANGLE OF AIM, LIKELY TARGETING THE GUNNER. ALTHOUGH NO INITIATION SYSTEM WAS FOUND, THERE WAS A POLE MARKED WITH A GREEN TARP APPROXIMATELY 10M FROM THE BLAST SEAT THAT COULD HAVE BEEN USED AS AN AIMING MARKER.

2/82 AAB S2 ASSESSMENT:	(b)(1)1.4c
Q-	
r)	0)(1)1.4c
, t	J(1)1.4C
7,	
AREA CONTROLLED BY	(b)(1)1.4c, (b)(6)
)1.4c
	RATIVE WITH USF. ENGAGING THIS
SHEIKH MAY PROVIDE INSIGHT II	
TERRORIST AFFILIATIONS THAT L	IVE IN THE AREA, LOCAL
ATMOSPHERICS AND INFORMAT	And the second s
USD-C G-2 ASSESSMENT: THE 14	1851NOV11 EFP ATTACK OCCURRED
WITHIN 305 METERS OF	(b)(1)1.4c, (b)(6)

(b)(1)1.4c, (b)(6)

SO IT IS PLAUSIBLE THAT HE WOULD HAVE INFORMATION ON THE INDIVIDUAL(S) OR GROUP'S RESPONSIBLE FOR EMPLACING THIS EFP.

BDA:

5 X USF WIA (1 X USF DOW, 1 X USF WIA, 3 X USF RTD) 1 X VEHICLE DAMAGED (MAXPRO)

15-November-11 Page 3 of 7



ENEMY:				COALITION:	17-00
KIA:	WIA:	DET:	KIA:	WIA:	ABD:
0	0	0	1	2	0

CIVILIAN:					
KIA:	WIA:	ABD:	KIA:	WIA:	ABD:
0	0	0	0	0	0

CCIR Status

SUMMARY: USF-I CCIR 12: Significant military actions or incidents involving USF,

ISF or Civilians regardless if there are casualties

GROUP: USD-C G3 SIGACT MANAGER

SUMMARY: USF-I DCG(O) IR 9: Significant Civilian and Military Casualties per CCIR

#12

GROUP: USD-C G3 SIGACT MANAGER

SUMMARY: CENTCOM IR 31: US / Non-US service member Kill in Action (KIA)

GROUP: USF-' 33 SIGACTS MGR

SUMMARY: USF-I DCG(O) IR 17: Any attack utilizing RKG-3, EFP, SVBIED and/or

PBIED

GROUP: USF-I J33 SIGACTS MGR

Capture Details

Casualty Details

CASUALTY COUNT: 2

15-November-11 Page 4of 7

113 08/08/2018

USCENTCOM FOIA 17-0112



BATTLE ROSTER NUMBER: Not Reported

FORCE TYPE: CF PARTY RESPONSIBLE: Unknown

AFFILIATION: Coalition CASUALTY TYPE: WIA

NATIONALITY: UNITED STATES SERVICE: Not Reported

CATEGORY: Urgent POSITION: Unknown

GROUP: Unknown STATUS: Unknown

ASSOCIATED EVENT: Not Reported

COMMENTS: Not Reported

HEAD WOUND: No CHEST/TORSO WOUND: No

ARM WOUND: No HAND WOUND: No

LEG WOUND: No FEET WOUND: No

CASUALTY COUNT: 1

BATTLE ROSTER NUMBER: Not Reported

FORCE TYPE: CF PARTY RESPONSIBLE: Unknown

AFFILIATION: Coalition CASUALTY TYPE: KIA

NATIONALITY: UNITED STATES SERVICE: Not Reported

CATEGORY: Urgent POSITION: Not Reported

GROUP: Unknown STATUS: Unknown

ASSOCIATED EVENT: Not Reported

COMMENTS: Not Reported

HEAD WOUND: No CHEST/TORSO WOUND: No

ARM WOUND: No HAND WOUND: No

LEG WOUND: No FEET WOUND: No

Target(s) of Attack

PRECEDENCE: Primary TYPE: Coalition

AFFILIATION: Coalition SECT: Unknown

DETAILS: Other NATIONALITY: UNITED STATES

15-November-11 Page 5 of 7

USCENTCOM FOIA 17-0112 114 08/08/2018



STATUS: Killed

DESCRIPTION: Not Reported

Indirect Fire Information

Vehicle/Convoy Details

NUMBER OF VEHICLES: 0

DISTANCE BETWEEN VEHICLES: 0 Meters

CONVOY SPEED: 0 MPH

NEAREST ECM DIST TO IED: 0 Meters

NEAREST ECM DIST TO VEHICLE STRUCK: 0 Meters

OTHER COUNTERMEASURES ON VEHICLE STRUCK: Not Reported

VEHICLE SUMMARY: Not Reported

DRUGREP Details

FACILITY TYPE: Not Reported

Drugs Found

Chemicals Found

Equipment Found

15-November-11 Page 6of 7

	Reintegration De	etails	
REINTEGRATION OPEN:			No
REINTEGRATION OPEN COMME	NTS:		No
NUMBER OF REINTEGRATEES:			300
	FOLLOW UP DATES	COMPLETED	COMPLETED DATE
VETTING DATE:	Not Reported	No	Not Reported
COMMUNITY TALK DATE:	Not Reported	No	Not Reported
REINTEGRATION DATE:	Not Reported	No	Not Reported
7 DAY FOLLOW UP:	Not Reported	No	Not Reported
30 DAY FOLLOW UP:	Not Reported	No	Not Reported
60 DAY FOLLOW UP:	Not Reported	No	Not Reported
90 DAY FOLLOW UP:	Not Reported	No	Not Reported
180 DAY FOLLOW UP:	Not Reported	No	Not Reported
REINTEGRATION CLOSED: No	REINTEGRATION CLOSED	REASON: Not Repor	ted
REINTEGRATION CLOSED COMM	ЛENTS:		No

15-November-11 Page 7 of 7



(722D EOD / 2nd PLT / Team 2-1)

141916CNOV11

2/82 AAB SUPPORTED BCT (b)(3), (b)(6)
TEAM LEADER

(b)(3), (b)(6) 2 ON SCENE COMM

38SMB3241699926 MGRS GRID LOCATION MSR TAMPA MSR

Sout DIRECTION OF

Blast
TYPE OF REPORT

EVENT CATEGORY

Unkno METHOD OF EM

SIGACT #: 20111114190 .38SMB3241099926

CIDNE #: BLAST-201111 1/9 91638SMB3241699926

CCIR: DCG-O CCIR #1

	CF	LN	IA/IP/NP	E	U.S. Civilian	Coalition
KIA	1	0	0	0	0	(
WIA	4 USCENTCOM	0 1 FOIA 17-0112	0	0	0	117.0







USCENTCOM FOIA 17-0112 118 0



Aerial / Map View of Site



Time

EOD Notification:

EOD FOB Departure:

EOD Scene Arrival:

EOD Scene Departure:

EOD Mission Complete:




119 0

USCENTCOM FOIA 17-0112



Scene Diagram



USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

120 0



Narrative / Background

CO/2-325 AIR convoy was trave 325 AIR Soldiers performed a s	t) TM 2-1 responded to an IED blast IVO J8SM eling south on MSR Tampa when the lead vehic econdary search IOT provide and clear a hast Team arrived on scene and dismounted under	cle was struck by an y LZ for MEDEVAC, a
conduct ost blast anal sis. D	ama e to the tar et vehicle consisted of	(b)(1)1.4c, (b)(1)1.4g
and	(b)(1)1.4c, (b)(1)1.4g	
(b)(1)1.4c, (b)(1)1.4g	No evidence of the initiatio system wa	s found. There were
secondary devices or explosive this attack.	e hazards found. There 🧳 s one USF KIA and	four USF WIA as a re

USCENTCOM FOIA 17-0112 121 0





EOD Team Leader Observations

<u>InitiationType</u> <u>Initiator</u> <u>Main Charge</u> <u>Container</u>

Unknown Directional-EFP Other

(SECRET // REL TO USA, ACGU) It is the EOD Team Leader a assessment that the IED was an EFP unknown initiation system. The struck vehicle was impacted near the top of the passenger side into a high angle of aim, likely targeting the gunner. Although n initiation system was found, there was marked with a green tarp approximately 10m from the blast seat that could have been used as an a marker.

USCENTCOM FOIA 17-0112 122 0







USCENTCOM FOIA 17-0112

SECRET // REL TO USA,

123 0




Evidence List

Item/Bag #	Quantity	Evidence		
1	2	(b)(1)1.4c		

USCENTCOM FOIA 17-0112



Photographs of Scene



Return to Aeri

USCENTCOM FOIA 17-0112



Photographs of Scene



Blast Seat

USCENTCOM FOIA 17-0112 126 0



Photographs of Scene



Blast Seat view from South

USCENTCOM FOIA 17-0112 127 0



Photographs of Scene



Blast Seat view from North West

USCENTCOM FOIA 17-0112 128 0



Photographs of Scene



West

Retur

USCENTCOM FOIA 17-0112



Photographs of Scene



South

Retur

130 0

USCENTCOM FOIA 17-0112



Photographs of Scene



East

Retur

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

131 0



Photographs of Scene



North

Retur

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

132




Photographs of Scene



Green Tarp on Pole

USCENTCOM FOIA 17-0112 133 0






Damage to TC side of vehicle

USCENTCOM FOIA 17-0112






Damage to TC side of vehicle

USCENTCOM FOIA 17-0112 135 0






Top View of armor penetration

USCENTCOM FOIA 17-0112 136 0






Armor Penetration

USCENTCOM FOIA 17-0112






Close up of armor penetration into top of TC side window

USCENTCOM FOIA 17-0112 138 0





Fragmentation Damage to TC side with


(b)(1)1.4c

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

139 0





MEAP Armor damage to TC side of vehicle

USCENTCOM FOIA 17-0112 140 0








View of armor penetration from inside vehicle

USCENTCOM FOIA 17-0112





Interior damage to rear driver's side of vehicle

USCENTCOM FOIA 17-0112



Photographs of Scene



(b)(1)1.4c

removed from inside vehicle

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

143 0



Photographs of Scene



(b)(1)1.4c

removed from inside vehicle

USCENTCOM FOIA 17-0112